


TOUCHSTONE TOUCHPAD – GLACIER WHITE/GOLD



TOUCHStone

SUMMARY

Designed to provide dual flush activation of the Mainsflush MFL140 toilet flush valve. The soft lines and the silky feel of the Touchstone touchpad bring a contemporary elegance to the bathroom. The sensory feedback of the electronics combine with the stunning design to bring a luxurious new experience to flushing your toilet. The inlaid solid gold flush logos add an understated touch of class.

FEATURES

- Stylish touchpad with a warm, silky feel and contemporary design
- Inlaid solid gold flush logos make this touchpad suited to the most luxurious bathrooms
- Operates on touch sensitive technology
- A gentle touch of the pad generates a subdued audio response and flushes the toilet.
- Suitable for elderly and disabled users
- The sound feature can be disabled at installation
- Strong, hygienic, secure and easy to install
- Can be located anywhere in the bathroom

MATERIALS

- Made from DuPont™ Corian® solid surface materials
- Inlaid with 9 carat solid gold
- 115mm x 77mm

COLOUR

- Glacier White with solid gold flush logo inlay

WARRANTY

- 12 Months

TECHNICAL INFORMATION

- Mainsflush part number: M2328
- Requires 240v power outlet
- Connects to the Mainsflush MFL140 valve
- Pre-set to provide a 2 second half flush and a 5 second full flush
- The touchpad has an in-built lockout period which requires a 5 second break between flushes
- Attaches by a mounting bracket screwed to the wall and a concealed grub screw accessible from below
- Designed and made in Australia
- Protected by Australian and International patents, trademarks and registered designs

Footnote: Corian® is a DuPont™ registered trademark for its solid surfaces

Disclaimer:

Products in this specification manual must by regulation be installed by licensed and registered trade people. The manufacturer/distributor reserves the right to vary specifications or delete models from their range without prior notification. Dimensions and set-outs listed are correct at time of publication however the manufacturer distributor takes no responsibility for printing errors.